

Table compiled by Albert Sauveur. To use, simply refer to figure in middle column; if in degrees Centigrade, read Fahrenheit equivalent in right-hand column; if in degrees Fahrenheit, read Centigrade equivalent in left-hand column.

-459.4 to 0		
C		F
-273	-459.4	---
-268	-450	---
-262	-440	---
-257	-430	---
-251	-420	---
-246	-410	---
-240	-400	---
-234	-390	---
-229	-380	---
-223	-370	---
-218	-360	---
-212	-350	---
-207	-340	---
-201	-330	---
-196	-320	---
-190	-310	---
-184	-300	---
-179	-290	---
-173	-280	---
-169	-273	-459.4
-168	-270	-454
-162	-260	-436
-157	-250	-418
-151	-240	-400
-146	-230	-382
-140	-220	-364
-134	-210	-346
-129	-200	-328
-123	-190	-310
-118	-180	-292
-112	-170	-274
-107	-160	-256
-101	-150	-238
-96	-140	-220
-90	-130	-202
-84	-120	-184
-79	-110	-166
-73	-100	-148
-68	-90	-130
-62	-80	-112
-57	-70	-94
-51	-60	-76
-46	-50	-58
-40	-40	-40
-34	-30	-22
-29	-20	-4
-23	-10	14
-17.8	0	32

Cartech.com Tech Center
Temperature Conversions (continued)

0 to 50		
C		F
-17.8	0	32.0
-17.2	1	33.8
-16.7	2	35.6
-16.1	3	37.4
-15.6	4	39.2
-15.0	5	41.0
-14.4	6	42.8
-13.9	7	44.6
-13.3	8	46.4
-12.8	9	48.2
-12.2	10	50.0
-11.7	11	51.8
-11.1	12	53.6
-10.6	13	55.4
-10.0	14	57.2
-9.4	15	59.0
-8.9	16	60.8
-8.3	17	62.6
-7.8	18	64.4
-7.2	19	66.2
-6.7	20	68.0
-6.1	21	69.8
-5.6	22	71.6
-5.0	23	73.4
-4.4	24	75.2
-3.9	25	77.0
-3.3	26	78.8
-2.8	27	80.6
-2.2	28	82.4
-1.7	29	84.2
-1.1	30	86.0
-0.6	31	87.8
0.0	32	89.6
0.6	33	91.4
1.1	34	93.2
1.7	35	95.0
2.2	36	96.8
2.8	37	98.6
3.3	38	100.4
3.9	39	102.2
4.4	40	104.0
5.0	41	105.8
5.6	42	107.6
6.1	43	109.4
6.7	44	111.2
7.2	45	113.0
7.8	46	114.8
8.3	47	116.6
8.9	48	118.4
9.4	49	120.2
10.0	50	122.0

Cartech.com Tech Center
Temperature Conversions (continued)

51 to 100		
C		F
10.6	51	123.8
11.1	52	125.6
11.7	53	127.4
12.2	54	129.2
12.8	55	131.0
13.3	56	132.8
13.9	57	134.6
14.4	58	136.4
15.0	59	138.2
15.6	60	140.0
16.1	61	141.8
16.7	62	143.6
17.2	63	145.4
17.8	64	147.2
18.3	65	149.0
18.9	66	150.8
19.4	67	152.6
20.0	68	154.4
20.6	69	156.2
21.1	70	158.0
21.7	71	159.8
22.2	72	161.6
22.8	73	163.4
23.3	74	165.2
23.9	75	167.0
24.4	76	168.8
25.0	77	170.6
25.6	78	172.4
26.1	79	174.2
26.7	80	176.0
27.2	81	177.8
27.8	82	179.6
28.3	83	181.4
28.9	84	183.2
29.4	85	185.0
30.0	86	186.8
30.6	87	188.6
31.1	88	190.4
31.7	89	192.2
32.2	90	194.0
32.8	91	195.8
33.3	92	197.6
33.9	93	199.4
34.4	94	201.2
35.0	95	203.0
35.6	96	204.8
36.1	97	206.6
36.7	98	208.4
37.2	99	210.2
37.8	100	212.0

Cartech.com Tech Center
Temperature Conversions (continued)

110 to 600		
C		F
43	110	230
49	120	248
54	130	266
60	140	284
66	150	302
71	160	320
77	170	338
82	180	356
88	190	374
93	200	392
99	210	410
100	212	413.6
104	220	428
110	230	446
116	240	464
121	250	482
127	260	500
132	270	518
138	280	536
143	290	554
149	300	572
154	310	590
160	320	608
166	330	626
171	340	644
177	350	662
182	360	680
188	370	698
193	380	716
199	390	734
204	400	752
210	410	770
216	420	788
221	430	806
227	440	824
232	450	842
238	460	860
243	470	878
249	480	896
254	490	914
260	500	932
266	510	950
271	520	968
277	530	986
282	540	1004
288	550	1022
293	560	1040
299	570	1058
304	580	1076
310	590	1094
316	600	1112

Cartech.com Tech Center
Temperature Conversions (continued)

610 to 1000		
C		F
321	610	1130
327	620	1148
332	630	1166
338	640	1184
343	650	1202
349	660	1220
354	670	1238
360	680	1256
366	690	1274
371	700	1292
377	710	1310
382	720	1328
388	730	1346
393	740	1364
399	750	1382
404	760	1400
410	770	1418
416	780	1436
421	790	1454
427	800	1472
432	810	1490
438	820	1508
443	830	1526
449	840	1544
454	850	1562
460	860	1580
466	870	1598
471	880	1616
477	890	1634
482	900	1652
488	910	1670
493	920	1688
499	930	1706
504	940	1724
510	950	1742
516	960	1760
521	970	1778
527	980	1796
532	990	1814
538	1000	1832

Cartech.com Tech Center
Temperature Conversions (continued)

1010 to 1500		
C		F
543	1010	1850
549	1020	1868
554	1030	1886
560	1040	1904
566	1050	1922
571	1060	1940
577	1070	1958
582	1080	1976
588	1090	1994
593	1100	2012
599	1110	2030
604	1120	2048
610	1130	2066
616	1140	2084
621	1150	2102
627	1160	2120
632	1170	2138
638	1180	2156
643	1190	2174
649	1200	2192
654	1210	2210
660	1220	2228
666	1230	2246
671	1240	2264
677	1250	2282
682	1260	2300
688	1270	2318
693	1280	2336
699	1290	2354
710	1310	2390
716	1320	2408
721	1330	2426
727	1340	2444
738	1360	2480
743	1370	2498
749	1380	2516
754	1390	2534
760	1400	2552
766	1410	2570
771	1420	2588
777	1430	2606
782	1440	2624
788	1450	2642
793	1460	2660
799	1470	2678
804	1480	2696
810	1490	2714
816	1500	2732

**Cartech.com Tech Center
Temperature Conversions (continued)**

1510 to 2000		
C		F
821	1510	2750
827	1520	2768
832	1530	2786
838	1540	2804
843	1550	2822
849	1560	2840
854	1570	2858
860	1580	2876
866	1590	2894
871	1600	2912
877	1610	2930
882	1620	2948
888	1630	2966
893	1640	2984
899	1650	3002
904	1660	3020
910	1670	3038
916	1680	3056
921	1690	3074
927	1700	3092
932	1710	3110
938	1720	3128
943	1730	3146
949	1740	3164
954	1750	3182
960	1760	3200
966	1770	3218
971	1780	3236
977	1790	3254
982	1800	3272
988	1810	3290
993	1820	3308
999	1830	3326
1004	1840	3344
1010	1850	3362
1016	1860	3380
1021	1870	3398
1027	1880	3416
1032	1890	3434
1038	1900	3452
1043	1910	3470
1049	1920	3488
1054	1930	3506
1060	1940	3524
1066	1950	3542
1071	1960	3560
1077	1970	3578
1082	1980	3596
1088	1990	3614
1093	2000	3632

**Cartech.com Tech Center
Temperature Conversions (continued)**

2000 to 2500		
C		F
1093	2000	3632
1099	2010	3650
1104	2020	3668
1110	2030	3686
1116	2040	3704
1121	2050	3722
1127	2060	3740
1132	2070	3758
1138	2080	3776
1143	2090	3794
1149	2100	3812
1154	2110	3830
1160	2120	3848
1166	2130	3866
1171	2140	3884
1177	2150	3902
1182	2160	3920
1188	2170	3938
1193	2180	3956
1199	2190	3974
1204	2200	3992
1210	2210	4010
1216	2220	4028
1221	2230	4046
1227	2240	4064
1232	2250	4082
1238	2260	4100
1243	2270	4118
1249	2280	4136
1254	2290	4154
1260	2300	4172
1266	2310	4190
1271	2320	4208
1277	2330	4226
1282	2340	4244
1288	2350	4262
1293	2360	4280
1299	2370	4298
1304	2380	4316
1310	2390	4334
1316	2400	4352
1321	2410	4370
1327	2420	4388
1332	2430	4406
1338	2440	4424
1343	2450	4442
1349	2460	4460
1354	2470	4478
1360	2480	4496
1366	2490	4514
1371	2500	4532

Cartech.com Tech Center
Temperature Conversions (continued)

2510 to 3000		
C		F
1377	2510	4550
1382	2520	4568
1388	2530	4586
1393	2540	4604
1399	2550	4622
1404	2560	4640
1410	2570	4658
1416	2580	4676
1421	2590	4694
1427	2600	4712
1432	2610	4730
1438	2620	4748
1443	2630	4766
1449	2640	4784
1454	2650	4802
1460	2660	4820
1466	2670	4838
1471	2680	4856
1477	2690	4874
1482	2700	4892
1488	2710	4910
1493	2720	4928
1499	2730	4946
1504	2740	4964
1510	2750	4982
1516	2760	5000
1521	2770	5018
1527	2780	5036
1532	2790	5054
1538	2800	5072
1543	2810	5090
1549	2820	5108
1554	2830	5126
1560	2840	5144
1566	2850	5162
1571	2860	5180
1577	2870	5198
1582	2880	5216
1588	2890	5234
1593	2900	5252
1599	2910	5270
1604	2920	5288
1610	2930	5306
1616	2940	5324
1621	2950	5342
1627	2960	5360
1632	2970	5378
1638	2980	5396
1643	2990	5414
1649	3000	5432